

Weathering Techniques - 1

Bill McMillan

Division 6

North Central Region, NMRA

Weathering tools

1. Model Master Acrylic Paint
 1. Burnt Sienna - 4607
 2. Burnt Umber - 4605
 3. Rust – 4675 (also Earth Red – 4707)
 4. Grimy Black - 4887
 5. Aluminum - 4677
 6. Flat White – 4769 (or Light Gray – 4765 / Camouflage Gray- 4766)
2. Paint Brushes – various sizes from extremely small to about ½”
3. Distilled Water
4. Windex (no ammonium if possible)

Weathering Techniques – 1 content

- 1. Rusted scrapes on freight cars**
- 2. Rust spots / streaks**

1. Rusty scrapes



2. Rust Spots / Streaks



Video: Weathering – 1 Rust Scrapes & Spots

This video may be viewed anytime on my YouTube channel.

Search for William A. McMillan and scroll the list to find this photo:





W

End of Weathering – 1

Weathering – 2 will continue with how to fade lettering and roof weathering and overall fading of the freight car or locomotive